

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18th STREET - SUITE 500 DENVER, COLORADO 80202-2466



ACCESS AGREEMENT

PROPERTY ADI						
3757-	59 F	ranklin	Street,	Jenrer,	(0 8	0205
Mailing Address (ldress): neet, Den	rer, (0	80 Z	05

I will allow Environmental Protection Agency (EPA) staff and EPA's authorized representatives to have access to my property identified above for the purpose of collecting soil samples. I understand that this service is provided at no cost to me.

I understand that this soil testing is part of an investigation of possible metals contamination in soils in the north Denver area. EPA is conducting this investigation as part of its responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act, a law also referred to as "Superfund".

Print Name Christine Charles

Print Name

Print Name

Phone Number

Please check the following if applicable:

I would like EPA to provide me with a portion of the sample, called a "split sample," that I may have analyzed at my own expense.

If you have any questions, please contact Ted Fellman at (303) 312-6119, or Marta Valentine from the Morrison Knudsen Corporation (EPA's contractor) at (303) 948-4693.

Your Comments:

PLEASE SIGN AND RETURN THIS ACCESS AGREEMENT TO OUR CONTRACTOR IN THE ENCLOSED PREPAID ENVELOPE. Soil sampling will take about 1 hour. The owner or resident need not be present. If you would like to be notified when we plan to sample your property, please state so in the Comments section and provide your phone number. Also, pet owners are asked to provide a phone number so that if necessary we may schedule the sampling at a time when the pet will be indoors or restrained. Thank you for participating in this important study of your neighborhood.

NOTE: If you are <u>not</u> the current property owner, and you are not a renter who wishes to forward this request to the owner, please state so in the Comments section and return this agreement unsigned.

E. 1026

To: Marta Walentine Fax #948-4010 From: Lynne Charles Date: 8/25/99

Dear Marta, Here is a copy of the inspection record for (3757-)59 Franklin 8t. I circled the R-3 next to occupancy, which is residential zonig.
This should allow us to go ahead with the soil testing the clone there, which can only be done there, writen com sent the in the back. I sent the in Please in the back. I sent the authorization in by mail. Please authorization in 303-292-0176 if you call me at 303-292-0176 if you need anything else. Ly

Herland non Ros Prosection 8/26/49 MAR

E-1026

INSPECTION RECORD CARD FOR CITY AND COUNTY OF DENVER

RRWRC COMM DIE DAG

		Ja ~	· // /·	17	_	- 9013	4249
Address Of Project	3/57-	$\frac{1}{2}$	anklin	36	Construction	Permit # / 0 / _	0517
Address Of Project	3	Construction	Type 72 ~	// Inh	Description	Structura/	K = 44.05
Occupaticy			Type =	000	pescribation _		

INSPECTIONS WILL NOT BE MADE UNLESS THIS CARD IS POSTED ON JOB SITE
NO INSPECTION WILL BE MADE UNTIL GENERAL AND ALL SUB CONTRACTORS NAMES ARE ON THIS CARD
REQUEST FOR INSPECTION: REFER TO AUTOMATED INSPECTION REQUEST SYSTEM BROCHURE OR THE BACK OF
CUSTOMER'S COPY OF #1-C OR 1-R PERMIT

Work Performed	Name of Contractor inspector's Signature	Date of inspection (Mo., day, Year)	Type of inspection Made	
GENERAL CONTRACTOR	Lune Charles	1,000,000		
CONCRETE - FTG.				
Inspector Sign Here			Footing	
FDN WALL	 	 	1.00,000	
Inspector Sign Here •		 	Foundation	
FDN INSULATION	<u> </u>	 	T Octionation	
Inspector Sign Here			Insulation	
WATERPROOFING & FDN. DRAIN		 	insolution	
Inspector Sign Here		 	Waterproofing & Fndn, Drain	
EXTERIOR WALL SHEATHING		 	•	
Inspector Sign Here)		 	Exterior Wall Sheathing	
FRAME	Kurt Olsen tilsen Kemala	Aug.	FRAME to be made after all Rough	
Inspector Sign Here		<i>'y</i>	Utility Installations have been	
magacior digit riore y		 	INSPECTED and APPROVED.	
It-SULATION / BATT		 	INOPECTED BIJUAPPROVED	
Inspector Sign Here	Morgan	5-5-99	 	
INSULATION / BLOWN IN	A. Justin	 		
Inspector Sign Here	Margan	5-5-99	 	
LATH	- January Control	12 =2 -/		
Inspector Sign Here		 	Lath	
DRY WALL	¥.	 	Latin	
Inspector Sign Here		 	Dry Wall	
ROOFING	``	 	loty (val)	
Inspector Sign Here •		 	Roofing - Siding	
GUTTER - DOWNSPOUTS		 	Hooling - Storing	
Inspector Sign Here		 	Gutter - Downspouts	
PLUMBING		 	Conter Downspous	
Inspector Sign Here	——————————————————————————————————————		Rough - Plumbing	
Inspector Sign Here			Final - Plumbing	
POOL PIPING -		 	Trillar-Fightonig	
WATER SERVICE DOMESTIC	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			
FIRE PROTECTION	PLUMBING	 		
Inspector Sign Here	I EOIADING	, 	Rough - Fire Protection	
Inspector Sign Here			Final - Fire Protection	
RANGE HOOD FIRE PROTECTION		 	Final - Fire Protection	
WATER SERVICE FIRE PROTECTION		 	 	
	IMAGE	 		
Inspector Sign Here	1000		Bouch Stoatded	
Inspector Sign Here	R. Asia	1/	Rough - Electrical	
	ELECTRICAL	01019	Final - Electrical	
RE ALARM Inspector Sign Here I	ELECTRICAL	 	Dough Sine Book and a	
Inspector Sign Here I		 	Rough - Fire Protection	
ACCESS CONTROL		 	Final - Fire Protection	
Inspector Sign Here		 		
Inspector Sign Here		 		
mapactor againment				